M. A. R. 57 (Rule 116)
Measurement Book

No. B 180029

ial No. Bill No 1 & final

ne of work ..... From ..... To .....

ne of Contractor of nature of Agency.....

e of commencement of work.....

Reference to last Measurement 8	ate	Full description, etc, of work 2	Number 3	Dimensions Length 4	Breadth 5	Depth 6	Contents 7	Reference to last Measurement 8
		Name of work: Improvements to road at Boundary Layout 11th Cross connecting to new Extn in Bagalakunte in W.No 14 T. Dasarahalli Sub-div						
		JOB code 014-17-000034 P code No P-3158						
		Est cost ₹ 30.00 Lakhs						
		Work Order No BBMP/EE/DD/WO/175/2017-18 dt 21.6.17						
		Agency Technical Manager (N) K.R.I.D.L						

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	11th cross	1×0.5	30.00	0.15	–	2.25 M2	
		1×0.5	30.0	0.15	–	2.25 "	
		1×0.5	30.0	0.15	–	2.25 "	
		1×0.5	13.0	0.15	–	0.975 "	
	Road 1	1×0.5	30.0	0.15	–	2.25 "	
		1×0.5	30.0	0.15	–	2.25 "	
		1×0.5	30.0	0.15	–	2.25 "	
		1×0.5	30.0	0.15	–	2.25 "	
		1×0.5	3.00	0.15	–	0.225 "	
	Road 2	1×0.5	30.0	0.15	–	2.25 "	
		1×0.5	30.0	0.15	–	2.25 "	
		1×0.5	30.0	0.15	–	2.25	

M. A. R. 57 (Rule 116)
Measurement Book

No. B 180035

al No. .....

e of work ..... From ..... To .....

e of Contractor of nature of Agency.....

of commencement of work.....

e	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
	2	3	4	5	6	7	8
		1×0.5	30.0	0.15	–	2.25 M2	
		1×0.5	15.0	0.15	–	1.125 "	
	12th cross	1×0.50	30.0	0.15	–	2.25 "	
		1×0.5	30.0	0.15	–	2.25 "	
		1×0.5	30.0	0.15	–	2.25 "	
					33.825	34.43M	18355=00
					at Rs	542.72	18685.86
							2746464-80
						Add 4% K.R.I.D.C Charges	24718=80
						Total	2993646=60

The finished Closed Road

2746133=00
247152=00
2993285=00

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ ಕಛೇರಿ
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measureme
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	(1) certified that the work done Satisfactorily (2) certified that the debris removed from the work spot.						

3-4-17

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು
ಬೆಂಗಳೂರು

M. A. R. 57 (Rule 116) p. 3158 No. B 180036

Measurement Book

BR 165/30/6/17

Audited and admitted for Rs. 2993285=

Passed by Cheque for Rs. 2494780=

Accounts Superintendent

B.B.M.P. Dasarahalli Division

Exe. Engineer

...e of Contractor of nature of Agency.....

...e of commencement of work.....

...From .....

...To .....

e	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
	2	3	4	5	6	7	8



ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಉಪ-ವಿಭಾಗ